GOATEST OF ALL TIME I TOY MODELS

ASSEMBLY GUIDE



TIME TO HAVE A LITTLE FUN >>

MINI SVD ASSEMBLY GUIDE



PARTS LIST

A. Bolt

B. Upper handguard

C. Lower handguard

D. Barrel

E. Charging handle

F. Dust cover

G. Receiver and stock

H. Magazine

I. Non-firing rounds

J. Scope

HARDWARE LIST

[1] Spring

[1] Bipod lock

[1] Screws

[1] Screwdriver with magnet



Push receiver (G) into barrel (D), insert the long screw where the holes align on top of the barrel.



Place handguards (B&C) around barrel (D). Push together and toward the stock until they snap into place.



Insert bipod lock over the front end of the handguards. Push bipod lock into place on the right side.



Insert charging handle (E) into receiver (G), handle facing right side. Put spring on bolt carrier (A) insert into rear grooves of charging handle.



Place dust cover (F) over the bolt carrier (A) by placing the front of the cover forward and push down until it rests in the groove in stock.



Attach scope (J) on receiver (G) and tighten top and bottom with large screws.



Load non-firing rounds into the magazine (H). Slide magazine in until it clicks into place. Time to show off your GoatGun!



SCAN FOR HOW TO VIDEO



GOAT GUNS"

GREATEST OF ALL TIME | TOY MODELS

GOATGUNS GOATGUNS.COM

LEGAL DISCLAIMER: GOATGUNS ARE MANUFACTURED AS NON-FIRING MODELS. ANY MODIFICATIONS OR REVERSALS DONE MAY BE SUBJECT TO LEGAL ACTION.